



Application Tooling Specification Sheet



Order No. 62203-0700

FEATURES

- Lip provided for positive alignment to connector assembly
- Inserts connector to a PCB without damage to the board
- Use tool 62203-0750 for removing connectors 170834-0001, 170834-0002, 170834-0012, and 170834-0013
- Use tool 62203-0710 for removing connectors 171963-0006 and 171963-0008

SCOPE

Products: zCD 16X connector assemblies. See Product List below for specific part numbers.

Product List

The following is a partial list of the product order numbers and their specifications this tool is designed to run. Updates to this list are available on <u>www.molex.com</u>.

Connector Series No.	Assembly Order No.			
170834	170834-0001	170834-0002	170834-0012	170834-0013
171963	171963-0006	171963-0008		
173359	173359-0001	173359-0002		

Notes:

- 1. See the following pages for tooling operation instructions.
- 2. These tools require a "Keep Out Zone" around the connector free of components. The rear of the connector should be .157" (4.00mm). If the area around the rear of the connector is less than 4.0mm the press block plate can be removed. To do this:
 - a. Remove the (2) M3 SHCS from the press block plate.
 - b. Remove the press block plate and place it on the top side of the press block.
 - c. Re-install the (2) M3 SHCS. See Figure 1.
- 3. The right and left sides should be .079" (2.0mm). See Figure 2.



Tool Setup

Depending on the number of connectors to be installed and/or the press used, this tool can be used alone or with a group of press-in tools, mounted in a 62201-95XX rail (ordered separately). See Figure 3.



Tool Installation

The 62201-95XX rail is available in a variety of lengths to accommodate multiple press-in tools.

Rail Part Number	Rail Overall Length	
62201-9501	24mm (0.94 in)	
62201-9502	72mm (2.83 in)	
62201-9503	156mm (6.14 in)	
62201-9504	216mm (8.50 in)	
62201-9509	254mm (10.0 in)	
62201-9511	305mm (12.0 in)	

Reference: This Press-In Tool is 32.0mm (1.26 in.) long.

Printed Circuit Board (PCB) Support

The zHD connector assembly requires significant force to press into the PCB. To prevent excessive PCB flexure and/or damage to the PCB, a support plate is strongly recommended directly beneath the connector hole pattern.

Due to the custom nature of every application, Molex does not offer any PCB support plate. The customer must furnish their own support plate.

When creating the PCB support plate, remember to allow clearance for the connector pins if they pass through the PCB thickness.

Tool Operation

- 1. Carefully insert, by hand, the connector assembly using the alignment pegs (2) for location on the PCB.
- 2. Place the press-in-tool on top of the connector assembly with the back guide surface of the tool against the back of the connector assembly. See Figure 4.

- 3. Place tool, connector, and PCB, in a press of suitable size and force, and seat the connector assembly as shown. The support plate (furnished by the customer) under the PCB must have clearance for the connector pins if they pass through the PCB.
- 4. Add the required number of M2 screws to secure the zHD assembly to the PCB. See sales drawings for correct mounting screw length.



CAUTION: To prevent injury, never operate any press without the guards in place. Refer to the press manufacturer's instruction manual.

CAUTION: Molex application tooling specifications are valid only when used with Molex connectors and tooling.

Contact Information

For more information on Molex application tooling please contact Molex at 1-800-786-6539.

http://www.molex.com

Release Date: 02-28-12 Revision Date: 12-09-15 **UNCONTROLLED COPY**