

- Ergonomically designed soft handles
- % Precisely designed crimping profiles with simple contact positioning
- % Easy handling due to outstanding force ratio
- Tool kits are easily installed into the Hand Crimp Tool or the 63816-0300 Power Crimp Head which is installed into the 63816-0200 (110 V) or the 63816-0250 (220 V) Battery Powered Tool.
- Many different Tool kits can be used with a single Battery Powered Tool.
- This tool is IPC/WHMA-A-620 Class 2 and RoHS compliant.

SCOPE

Products: "KK®" .156 Centers Crimp Terminals, 18-30 AWG.

Terminal	Terminal Order No.					Wire Size		Insulation Diameter		Strip Length	
Series No.	Loose Piece		* Reel		AWG	mm²	mm	ln.	mm	ln.	
	08-01-0102	08-05-0104	08-01-0101	08-06-0101	18-24	0.80-0.20	1.78-2.79	.070110	3.06-3.96	.120156	
	08-01-0122	08-06-0102	08-01-0121	08-05-0103							
1797	08-01-0124	08-07-0102	08-01-0123	08-07-0101							
	08-03-0102		08-03-0101								
	08-01-0106	08-05-0106	08-01-0105	08-05-0105	24-30	0.20-0.05	0.76-1.78	.030070	3.06-3.96	.120156	
	08-01-0126		08-01-0125							.120130	
4366	08-03-0304		08-05-0301	40-01-1194	18-24	0.80-0.20	1.78-2.79	.070110	3.06-3.96	.120156	
	08-05-0302		08-03-0303	50-36-1873							
			08-05-0305								
4573	08-05-0304	08-03-0306	08-05-0303	08-03-0305	24-30	0.20-0.05	0.76-1.78	.030070	3.06-3.96	.120156	
* Customer to cut off terminal from reel: 0.25mm (.010") maximum Cut-off Tab.											

DEFINITION OF TERMS



The above terminal drawing is a generic terminal representation. It is not an image of a terminal listed in the scope.

Doc No: ATS-6381166HM Revision: D

Release Date: 08-02-06 Revision Date: 04-24-12 **UNCONTROLLED COPY**

BEND UP

Insulation Crimp Note:

Due to the terminal's insulation grip design and/or insulation diameter range, this tool uses "overlap" form geometry in the insulation punch. This produces an overlap insulation crimp (A620 - compliant). While the insulation punch profile may appear "lopsided", this is a normal condition for this tool. See figure to the right. (Some tools with multiple crimp pockets may not have the "overlap" profile on all pockets).



CONDITIONS:

After crimping, the conductor profiles should measure the following (see notes below).

	Wire Size		Conductor Crimp				Pull Force		Profile	
Terminal Series No.			Height (Ref)		Width (Ref)		Minimum		FIOING	
	AWG	mm ²	mm	ln.	mm	In.	N	Lb.	Α	В
	18	0.80	0.92-1.02	.036040	1.93	.076	111.2	25.00	Х	
1797	20	0.50	0.91-1.01	.035039	1.93	.076	66.7	15.00	Х	
1797	22	0.35	0.91-1.01	.035039	1.93	.076	53.4	12.00	Х	
	24	0.20	0.89-0.99	.034038	1.93	.076	31.1	7.00	Х	
	18	0.80	0.92-1.02	.036040	1.93	.076	111.2	25.00	Х	
1266	20	0.50	0.91-1.01	.035039	1.93	.076	66.7	15.00	Х	
4366	22	0.35	0.91-1.01	.035039	1.93	.076	53.4	12.00	Х	
	24	0.20	0.89-0.99	.034038	1.93	.076	31.1	7.00	Х	
	24	0.20	0.85-0.95	.033037	1.68	.066	31.1	7.00		Х
1707	26	0.12	0.80-0.90	.031035	1.68	.066	17.8	4.00		Х
1797	28	0.08	0.78-0.88	.030035	1.68	.066	11.1	2.50		Х
	30	0.05	0.77-0.87	.030034	1.68	.066	6.7	1.50		Х
	24	0.20	0.85-0.95	.033037	1.68	.066	31.1	7.00		Х
4573	26	0.12	0.80-0.90	.031035	1.68	.066	17.8	4.00		Х
4070	28	0.08	0.78-0.88	.030035	1.68	.066	11.1	2.50		Х
	30	0.05	0.77-0.87	.030034	1.68	.066	6.7	1.50		Х

Tool Qualification Notes:

- 1. Pull Force should be measured with no influence from the insulation crimp.
- 2. The above specifications are guidelines to an optimum crimp.
- 3. Wires with tinned conductors will have higher pull strength than bare copper.

Note:

A crimp height chart is provided with this manual as <u>Reference Only</u>. Due to the wide range of wires, strands, insulation diameters, and durometers, actual crimp height measurements may very slightly. An occasional, destructive, pull force test should be preformed to check hand tool crimp. Pull Force value Must exceed the Minimum pull force specifications listed on this page.

CAUTION: Install only Molex terminals listed above with this tool. Do not crimp hardened objects as damage can occur to the tool or die.

INSTALLATION

To install the Tool Kit into the Power Crimp Head follow the steps below:

Anvils and Punches Installation



- 1. Insert the Anvils into the bottom slots of the nest. Install the M4 x 10 long BHCS and tighten in place.
- 2. Insert the Punches into the top slots of the nest. Install the M4 x 18 long BHCS and tighten in place. See Figure 1.

Locator Installation and Removal

Follow the steps below to install or replace the locator. See Figure 2.

To install the locator

1. Position the locator with the hole over the brass pivot shaft and snap it into place.

To remove the locator

- 1. Open the crimp hand tool.
- 2. Swing the existing locator open and away from the hand tool.
- 3. Firmly press down on the brass pivot shaft with your thumb, while pulling the locator up. Slip the locator off the top of the brass pivot shaft.



OPERATION

Open the tool by squeezing the handles together, at the end of the closing stroke, the ratchet mechanism will release the handles, and the hand tool will spring open.

Doc No: ATS-6381166HM Release Date: 08-02-06 Revision Date: 04-24-12

Crimping Terminals

- 1. Select the desired terminal listed in the preceding charts.
- 2. Swing the terminal locator away from the crimp tool shown in Figure 4. Some terminals with large insulation grips may interfere with the crimp tooling when swinging the locator into position. The terminal must then be loaded into the locator in the closed/crimp position.



- 3. When using the locator, press down on the wire stop on the locator as shown in Figure 4. Insert the proper terminal into the proper nest opening. Make sure when choosing the nest opening, it will correspond with the A or B profile on the hand tool.
- 4. Return the locator to its original position.
- 5. Insert the proper wire over the terminal. Some large O.D. wires may need to be placed into the terminal before closing the tool. Gently touch the wire stop with the end of the wire. See Figure 5.
- 6. Compress the terminal by squeezing the tool handles until the ratchet mechanism cycle has been completed. Release handles to open the jaws.
- 7. Remove the crimped terminal from the terminal locator by pressing down on the wire stop and gently pulling on the wire. The terminal locator can be in either position.
- 8. Visually inspect the crimped terminal for proper crimp location.

Note: The tamper proof ratchet action will not release the tool until it has been fully closed

For the Battery Power Tool:

- 1. Cycle the Battery Power Tool to crimp the terminal to the wire.
- 2. Remove the crimped terminal from the terminal locator by pressing down on the wire stop and gently pulling on the wire. The terminal locator can be in either position.
- 3. Visually inspect the crimped terminal for proper crimp location.

Locator Replacement

See the parts list on the last page of this document for the proper locator order number. Follow the steps below to replace the locator.

- 1. Open the crimp hand tool.
- 2. Swing the existing locator open and away from the hand tool.
- 3. Firmly press down on the brass pivot shaft with your thumb, while pulling the locator up. Slip the locator off the top of the brass pivot shaft. See Figure 6.
- 4. Replace it with the proper locator by putting over the brass pivot shaft and snapping it into place.



Maintenance

It is recommended that each operator of the tool be made aware of, and responsible for, the following maintenance steps:

- 1. Remove dust, moisture, and other contaminants with a clean brush, or soft, lint free cloth.
- 2. Do not use any abrasive materials that could damage the tool.
- 3. Make certain all pins; pivot points and bearing surfaces are protected with a thin coat of high quality machine oil. Do not oil excessively. The tool was engineered for durability but like any fine piece of equipment it needs cleaning and lubrication for a maximum service life of trouble free crimping. Use a 30 weight automotive (light) oil used at the oil points, every 5,000 crimps or 3 months, shown in Figure 7A or 7B will significantly enhance the tool life.
- Wipe excess oil from hand tool, particularly from crimping area. Oil transferred from the crimping area onto certain terminations may affect the electrical characteristics of an application.
- 5. When tool is not in use, keep the handles closed to prevent objects from becoming lodged in the crimping dies, and store the tool in a clean, dry area.

Miscrimps or Jams

Should this tool ever become stuck or jammed in a partially closed position, **Do Not** force the handles open or closed. The tool will open easily by pressing the ratchet release lever. See Figure 8.

How to Adjust Tool Preload (See Figure 8)

This hand tool is factory preset to 25-45 LBS. preload. It may be necessary over the life of the tool to adjust tool handle preload force. Listed below are the steps required to adjust the crimping force of the hand tool to obtain proper crimp conditions:

1. Remove or fold back the handle grip from the handle to expose the eccentric axle and setting wheel.

2. Remove the locking screw with a 2mm hex



wrench. The wrench set (63810-0101), is not supplied. It is sold separately from the hand tool.

Doc No: ATS-6381166HM Revision: D

Release Date: 08-02-06 Revision Date: 04-24-12

- 3. Turn the eccentric axle and setting wheel with the wrench or pliers Counter-clockwise (CCW) to increase handle force.
- 4. Replace the locking screw, aligning the nearest notch in the setting wheel to locking screw.
- 5. Replace the handle grip.
- 6. Check the crimp specifications or conduct a pull test after tool handle preload force is adjusted.

Warranty

This tool is for electrical terminal crimping purposes only. This tool is made of the best guality materials. All vital components are long life tested. All tools are warranted to be free of manufacturing defects for a period of 30 days. Should such a defect occur, we will repair or exchange the tool free of charge. This repair or exchange will not be applicable to altered, misused, or damaged tools. This tool is designed for hand use only. Any clamping, fixturing, or use of handle extensions voids this warranty.

CAUTION: Molex crimp specifications are valid only when used with Molex terminals and tooling.

CAUTIONS

- 1. Manually powered hand tools are intended for low volume or field repair. This tool is NOT intended for production use. Repetitive use of this tool should be avoided.
- 2. Insulated rubber handles are not protection against electrical shock.
- 3. Wear eye protection at all times.
- 4. Use only the Molex terminals specified for crimping with this tool.

Certification

Molex does not certify or re-certify commercial grade hand tools but rather supplies the following guidelines for customers to re-certify hand tools.

- % This tool is qualified to pull force only. To re-certify, crimp a terminal to a wire, which has been stripped 12.7mm (1/2") long, so there is no crimping of the insulation. Pull the terminal and wire at a rate no faster than 25mm (1.00") per minute. See the Molex web site for the Quality Crimp Handbook for more information on pull testing.
- % If the tool does not meet minimum pull force values, handle preload should be increased and the pull test rerun, (See How To Adjust Preload).
- % When the hand tool is no longer capable of achieving minimum pull force, it should be taken out of service and replaced.

The chart below shows all applications for this Tool Kit.

Tool Kit Order No.	Tool Order no.	Tool Description	Power Head Order No.	Adapter Description	Figure No.
	63810-0100	Hand Crimp Frame (Short)	N/A	N/A	9
63811-6670	63810-0400	Hand Crimp Frame (Long)	N/A	N/A	9
03011-0070	63816-0200	Battery Power Tool (110 V)	63816-0300	Power Crimp Head	10
	63816-0250	Battery Power Tool (220 V)	63816-0300	Power Crimp Head	10

Applications for the T	ool Kit
Hand Crimp Tool	Battery Powered Tool
TOOLING KIT COLING KIT COLING COLING FRAME LONG AND SHORT	POWER TOOLING KIT BATTERY POWERED TOOL CRIMP HEAD CRIMP HEAD CRIMP HEAD CRIMP HEAD CRIMP HEAD CRIMP HEAD CRIMP HEAD CRIMP HEAD
Figure 9	Figure 10

WARNING: NEVER operate service, install tool kits, or adjust the Power Crimp Head without proper instruction and without first reading and understanding the instructions in the proper Manual or Specification Sheet. See Chart above for the correct Manual or Specification Sheet.

WARNING: NEVER install tooling or service this tool while it is into any power source. Make sure the power is turned off.

CAUTION: Keep fingers away from the crimping area when operating this tool. It may cause severe injury.

CAUTION: Wear safety glasses when operating or serving this tool.



Itana Numahan	Order Number	Description	Quentity	
Item Number	Order Number	Description	Quantity	
1	63810-0100	Hand Crimp Frame (Short)	1	
2	63810-0101	Wrench Set (Not included)	0	
3	63810-0102	Locator Base	1	
4	63810-0103	Repair Kit (Not included)	0	
5	63811-6670	Tool Kit with Locator	1	
6	63811-6675	Locator (only)	REF	



Revision: D

Doc No: ATS-6381166HM Release Date: 08-02-06 Revision Date: 04-24-12

POWER HEAD PARTS LIST

Item	Order No	Engineering No.	Description	Quantity	
1	63816-0300	63816-0300	Power Crimp Head	1	
2	63811-6670	63811-6670	Tool Kit	1	



http://www.molex.com

Doc No: ATS-6381166HM Revision: D

Release Date: 08-02-06 Revision Date: 04-24-12